



STRENGTH AND TRUST

**INDUSTRY:**

Grain / Port

**PROJECT TYPE:**

Millwright / Industrial Service

**PROJECT OVERVIEW:**

Omega Morgan's Millwright team was called in to assess and correct the issues that were going on with the Spout #3. After determining that the issues were being caused by the main support pivot pin responsible for steering and supporting the spout was fractured, our Millwright team arranged a crew, ocean-going barge, tug service, scaffolding services and derrick barge crane to replace the faulty pivot pin.

**EQUIPMENT USED:**

- Ocean-going Barge
- Tug Boats
- Scaffolding
- Derrick Barge Crane
- 150' Manlift

**PROJECT:**

# INDUSTRIAL GRAIN SPOUT REPAIR

